

## Equipment

FIN

21528

INSULATED

~~REFRIGERATED~~MECHANICALLY  
REFRIGERATED~~HEATED~~~~MECHANICALLY  
REFRIGERATED  
AND HEATED~~~~MULTI-  
TEMPERATURE~~

## Certificate

## Issued pursuant to the Agreement on the International Carriage of Perishable Foodstuffs and on the Special Equipment to be used for such Carriage (ATP)

1. Issuing authority: **Natural Resources Institute Finland (Luke)**  
**Luonnonvarakeskus (Luke)**
2. Equipment: Lorry / Kuorma-auto / Lastbil
3. Registration number: MYR-149 Vehicle identification number: YS2P6X200L2173561  
allotted by: Liikenne- ja viestintävirasto Traficom, PL 320, 00059 TRAFICOM, FINLAND  
Insulated box serial number: »12657« Fokor, manuf: 09-2020
4. Owner or operated by: LEMPÄÄLÄN AUTOKULJETUS OY  
Kannistentie 141, 33880 LEMPÄÄLÄ, FINLAND
5. Submitted by: FOKOR OY  
Kuivakorventie 1, 30300 FORSSA, FINLAND
6. Is approved as: **FRC**
- 6.1 With one or more thermal appliances which is (are): Thermo King, No. GLW1260984, refr: R452a
- 6.1.1 Independent; 6.1.2 Not independent; 6.1.3 Removable; 6.1.4 Not removable.
7. Basis of issue of certificate:
- 7.1 This certificate is issued on the basis of:
- 7.1.1 Tests of equipment; 7.1.2 Conformity with a reference item of equipment; 7.1.3 A periodic inspection.
- 7.2 Specify:
- 7.2.1 The testing station: Luonnonvarakeskus Vihti, Finland ISO-LABET Castelo Branco, Portugal
- 7.2.2 The nature of the tests: § 2 § 4
- 7.2.3 The number(s) of the report(s): 3/2019 10A00063
- 7.2.4 The K coefficient: 0,384 W/m<sup>2</sup>°C
- 7.2.5 The effective refrigerating capacity at an outside temperature of 30 °C and an inside temperature of: Nominal capacity  
± 0 °C 11530 W  
- 10 °C 8905 W  
- 20 °C 6279 W
- 7.3 Number of openings and special equipment
- 7.3.1 Number of doors: rear door(s): 3 side door(s): 1
- 7.3.2 Number of vents: No vents 7.3.3 Hanging meat equipment: No
- 7.4 Others: No double deck rails
8. This certificate is valid until: **09-2026**
- 8.1 Provided that:
- 8.1.1 The insulated body and, where applicable, the thermal appliance is maintained in good condition; and
- 8.1.2 No material alteration is made to the thermal appliances;
9. Done by:
10. On: 22.4.2021



*Pekka Rantti*  
Pekka Rantti  
Sertifointipäällikkö

**Natural Resources Institute Finland (Luke)**  
**Luonnonvarakeskus (Luke)**

PL 2, FI-00791 HELSINKI, Finland  
Email: atp-todistukset@luke.fi, Phone: +358 295326000  
www.luke.fi

Tiedoksi: Ruokavirasto  
Tulli

Maksu: 120 € (MMM:n asetus 1252/2019)